Qty:

20 Um:

Each

Date: User: Thursday, 17/04/2008 10:59:14 AM

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

: WEARPAD

: D35649

: N/A

: D

. D3564 REV D

: 30/04/2008

Customer

: CU-DAR001 Dart Helicopters Services

Type

S.O. No. :

Job Number : 38656 **Estimate Number** : 12784

P.O. Number

: 17/04/2008 This Issue

: NC Prsht Rev.

: // First Issue

: 38408 **Previous Run**

Written By

Checked & Approved By

Comment

New Issue 07-03-08 ec As per Rev C 07-07-09 JLM Est Rev:B

Est Rev:C As per Rev D 07-09-09 JLM Verified By:EC

: SMALL /MED FAB

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0

M304S16GA

Comment: Qty.: 1.1550 sf(s)/Unit Total: 23.1000 sf(s) M304S16GA Stainless steel sheet 0.063" thick

Batch: 167773

2.0

WATER JET

FLOW WATER JET

304/316 .063 Sheet



Comment: FLOW WATER JET

*****(D3564-1F)***** 1-Cut as per Dwg D3564

Dwg Rev:_

Prog Rev:_

B 8-4-23

2-Deburr if necessary

3.0

QC2

INSPECT PARTS AS THEY COME OFF MACHINE



8-4-23


Comment: INSPECT PARTS AS THEY COME OFF MACHINE



Comment: SECOND CHECK

BRAKE NC

SECOND CHECK



5.0

NC BRAKE

Comment: NC BRAKE

Deburr if necessary

Form on Brake as per Dwg D3564 using Jigs DT

80 08/05/15

Dart Ae	rospace	Ltd								
W/O:			WC	ORK ORDER CHAN	IGES					****
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			· · · · · · · · · · · · · · · · · · ·							
Part No	: <u></u>	PAR #:	Fault Cate	gory:	NCR	: Yes N	o DQ	۹:	_ Date: _	
						QA: N/C	Close	d:	Date:	
NCR:		· \	WORK ORDI	ER NON-CONFORI	MANCE	(NCR)				
DATE	CTED	Description of NC					Verification		Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	n	Sign & Date	Secti		Chief Eng	QC Inspector
,										
							- Same			
		•								

NOTE: Date & initial all entries

Date:	Thursday, 17/04/2008 10:59:14 AM	
User:	Julie Lecocq	Process Sheet
Custo	mer: CU-DAR001 Dart Helicopters Se	vices Drawing Name: WEARPAD
Job Nun	nber: 38656	Part Number: D35649
Job Number		
Seq. #:	Machine Or Operation:	Description :
•	Form Joggle as per Dwg D3	
		SD 28/05/15
6.0	QC5	INSPECT WORK TO CURRENT STEP
Co	omment: INSPECT WORK TO CURF Ensure joggle as per dwg D	
7.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
Co	omment: LARGE FABRICATION RE	
	Qty Description	M 107-962 -4105959
	A/R 2059B Hardcoat Weld hardcoat as per Dwg	03564 08-65-22. 50.
8.0	QC10	VISUAL INSPECTION OF GROUND WELDS
	IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	SPOUND WELDS
9.0	QC5	INSPECT WORK TO CURRENT STEP
9.0		30 m
Co	omment: INSPECT WORK TO CURF	SELT OFFI
10.0	POWDER COATING	POWDER COATING
		M105642 (5#1 319.1)
C	pmment: POWDER COATING Powder Coat Grey Sandtey	(Ref. 4.3.5.6) as per QSI 005 4.3
11.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION #4 1335649
		AS IIIIII
	omment: INSPECT POWDER COAT	
12.0	PAĆKAGING 1	PACKAGING RESOURCE #1
Co	omment: PACKAGING RESOURCE	#1
	Identify and Stock Location:	-P 18 m. 1 08/05/26
,		

W/O:		✓ WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			1				

Part No:	PAR	#: Fault Cat	tegory:	NCR: Yes	No	DQA:	Date:	
				QA: N	I/C C	losed:	Date:	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)								
		STED Description of NC		Corrective Action Section B			Annroyal	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	QC Inspector			
						·					
*								,			

NOTE: Date & initial all entries

Date:

Thursday, 17/04/2008 10:59:14 AM

User:

Julie Lecocq

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 38656

Part Number: D35649

Job Number:



Seq. #:

Machine Or Operation:

Description:

13.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE



Job Completion



Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	*	PAR #: Fault Category:	NCR: Ye	s No DQ	A :	Date:					
			QA	: N/C Close	d:	Date:					

NCR:		V	WORK ORDER NON-CONFORMANCE (NCR)								
		Description of NC	Corrective Action Section B			Verification		Ammassal			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector			
					:						

NOTE: Date & initial all entries

DART AEROSPACE LTD	Work Order:	3865 <i>4</i>
Description: Wearshoe	Part Number:	D3564-9
Inspection Dwg: D3564 Rev: D		Page 1 of 1

	FIRST A	RTICLE INSP	ECTION	CHEÇKL	IST	
	X	First Article	F	Prototyp	е	
Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension	Tolcranoc	Dimension	Accept	Reject	Inspection	Comments
3.227	+/-0.010	3.224	*			
2.432	+/-0.010	2,434	半			
2.50	+/-0.030	02.G	XE			
6.000	+/-0.010	6,001	*			
12.104	+/-0.010	12.104	*			
18.000	+/-0.010	600.81	*			
18.000	+/-0.010	18.000	*			
18.00	+/-0.030	18.00				
9.00	+/-0.030	Ÿ. 6 0	*			
11.50	+/-0.030	11.50	*			
0.300 x 0.300	+/-0.010	304 x306	*			
Ø0.188	+0.005/-0.001	.191	*			
R0.375	+/-0.010	,375	X			
0.063	+/-0.010	,060	×			
		A. A. (14 A.).				
Measured by:	B	udited by:		Pro	totype Approva	: N/A
Date:	8-4-23	Date:	B oct 22		Date	: N/A
Rev Date A 08.01.16	Change New Issue				Revised by	Approve

